

Ref #	Hits	Search Query	DBs	Default Operator	Plurals	Time Stamp
L1	0	((laser adj welding) and (aluminum or magnesium) and ((heat or heating or heated) near (beside or supplement or next))).clm.	US-PGPUB; USPAT	OR	ON	2005/11/01 13:42
L2	0	((laser adj welding) and ((heat or heating or heated) near (beside or supplement or next))).clm.	US-PGPUB; USPAT	OR	ON	2005/11/01 13:40
L3	0	((laser adj welding) and (aluminum or magnesium) and ((heat or heating or heated) near (beside or supplement or next)) and (porosity adj free)).clm.	US-PGPUB; USPAT	OR	ON	2005/11/01 13:41
L4	0	((laser adj welding) and ((heat or heating or heated) near (beside or supplement or next)) and (porosity adj free)).clm.	US-PGPUB; USPAT	OR	ON	2005/11/01 13:41
L5	0	((laser adj welding) and (aluminum or magnesium) and ((extend or slow or extended or slowing or increase or decrease) near solidification)).clm.	US-PGPUB; USPAT	OR	ON	2005/11/01 13:42
L6	0	((laser adj welding) and ((extend or slow or extended or slowing or increase or decrease) near solidification)).clm.	US-PGPUB; USPAT	OR	ON	2005/11/01 13:42

Ref #	Hits	Search Query	DBs	Default Operator	Plurals	Time Stamp
L1	0	(laser near welding) and (aluminium or aluminum or magnesium) and (solidif\$8 near (pool or puddle)) and ((heat or heating or heated) near (pool or puddle))	USOCR	OR	ON	2005/11/01 12:42
L2	0	(laser near welding) and (aluminium or aluminum or magnesium) and ((heat or heating or heated) near (pool or puddle))	USOCR	OR	ON	2005/11/01 12:42
L3	0	(laser near welding) and ((heat or heating or heated) near (pool or puddle))	USOCR	OR	ON	2005/11/01 12:42
L4	0	(laser near welding) and (aluminium or aluminum or magnesium) and (solidif\$8 near (pool or puddle)) and ((heat or heating or heated) near (pool or puddle))	US-PGPUB; USPAT; EPO; JPO; DERWENT	OR	ON	2005/11/01 12:43
L5	15	(laser near welding) and (aluminium or aluminum or magnesium) and ((heat or heating or heated) near (pool or puddle))	US-PGPUB; USPAT; EPO; JPO; DERWENT	OR	ON	2005/11/01 12:56
L6	7	(laser near welding) and (aluminium or aluminum or magnesium) and (solidif\$8 near (pool or puddle))	US-PGPUB; USPAT; EPO; JPO; DERWENT	OR	ON	2005/11/01 13:27
L7	6	(laser near welding) and (aluminium or aluminum or magnesium) and (solidif\$8 near (slow or slowing or extended or extend or increase or decreased))	US-PGPUB; USPAT; EPO; JPO; DERWENT	OR	ON	2005/11/01 13:28

Ref #	Hits	Search Query	DBs	Default Operator	Plurals	Time Stamp
L1	0	(laser near welding) and (solidif\$6 near (pool or puddle) and (heat or heating or heated) near (pool or puddle))	USOCR	OR	OFF	2005/11/01 13:46
L2	0	(laser near welding) and ((heat or heating or heated) near (pool or puddle))	USOCR	OR	OFF	2005/11/01 13:47
L3	0	(laser near welding) and (solidif\$6 near (pool or puddle))	USOCR	OR	OFF	2005/11/01 13:47
L4	0	(laser near welding) and (solidif\$6 near (slow or slowing or extended or extend or increase or decrease))	USOCR	OR	OFF	2005/11/01 13:47
L5	1	(laser near welding) and (solidif\$6 near (pool or puddle) and (heat or heating or heated) near (pool or puddle))	US-PGPUB; USPAT; EPO; JPO; DERWENT	OR	OFF	2005/11/01 13:47
L6	22	(laser near welding) and ((heat or heating or heated) near (pool or puddle))	US-PGPUB; USPAT; EPO; JPO; DERWENT	OR	OFF	2005/11/01 13:50
L7	15	(laser near welding) and (solidif\$6 near (pool or puddle))	US-PGPUB; USPAT; EPO; JPO; DERWENT	OR	OFF	2005/11/01 13:56
L8	1	(laser near welding) and (solidif\$6 near (slow or slowing or extended or extend or increase or decrease))	US-PGPUB; USPAT; EPO; JPO; DERWENT	OR	OFF	2005/11/01 13:50